Page 1

Comment: SECOND CHECK

Form innocess

Dart Ae	rospace Ltd								
W/O:		WORK ORDER CHANGES							
DATE	STEP	PR	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	

						<u> </u>			
Part No):	PAR #:	Fault Category:	NCR: Ye	s No DQ	A:	_ Date: _		
r				QA	: N/C Close	d:	Date: _		
NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
			0				I	T	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC	Corrective Action Section B			Verification		A		
DATE	STEP	Section A			Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		
						,				

NOTE: Date & initial all entries

Thursday, 10/25/2007 10:12:24 AM Date: User: ' Kim Johnston **Process Sheet** Drawing Name: SPACER BLOCK Customer: CU-DAR001 Dart Helicopters Services Job Number: 35365A Part Number: D3193041 Job Number: Description: Seq. #: Machine Or Operation: HAND FINISHING RESOURCE #1 HAND FINISHING1 6.0 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 POWDER COATING 7.0 POWDER COATING m 19700 Comment: POWDER COATING Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSION QC3 8.0 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 08-02-RIVET 9.0 MS20426AD37 Total: 64.0000 Each(s) Comment: Qty.: 8.0000 Each(s)/Unit Pick: Qty Part Number Description Batch M1 269 8 MS20426AD3-7 Rivet M NUTPLATE MS21073L4 10.0 Comment: Qty.: Total: 32.0000 Each(s) 4.0000 Each(s)/Unit Pick: Description Batch Qty Part Number m102354 08-02-20 Nut Plate 4 MS21073L4 SMALL & MEDIUM FAB RESOURCE 1 11.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 08.02-22 Assemble D3193-041 as per Dwg D3193 12.0 QC5 Comment: INSPECT WORK TO CURRENT STEP

Dart Aerospace Ltd

W/O:		WORK ORDER CHA	WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	Ву	By Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
				·					

Part No):	PAR #: Fault Category:	NCR: Yes	NO DQ	⊥ A: <u> </u>	Date: <u> </u>	el ca/26		

QA: N/C Closed: ____ Date: ___

NCR:			WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Verification		T						
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector				
,												
<u> </u>		<u>, </u>										
٠.												
					1							

NOTE: Date & initial all entries

Date: Üser: '

Thursday, 10/25/2007 10:12:24 AM

Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SPACER BLOCK

Job Number: 35365A

Part Number: D3193041

Job Number:



Seq. #:

Machine Or Operation:

Description:

13.0

QC21

FINAL INSPECTION/W/O RELEASE





Comment: FINAL INSPECTION/W/O RELEASE

Job Completion





Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
, see										
	-									
Part No	·	PAR #: Fault Category:	NCF	R: Yes	No DQ	A :	_ Date: _			
				QA:	N/C Close	d:	Date:			

NCR:			WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B	Verification							
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector				
•												
		÷ .										
		:										
						r.						
						,						

NOTE: Date & initial all entries



DESIG	"A	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECK	(ED	APPROYED	DRAWING NO.	REV. C
	W	At-	D3193 SHEET	1 OF 1
DATE			TITLE	SCALE
05.0	9.29		SUPPORT BRACKET ASSEMBLY	1:2
Α		03.06.09	NEW ISSUE	
В		03.12.22	MANUFACTURED BY DART	
_		05 00 00	10004004D7 7 WAS MC00406AD7	5


Α	03.06.09	NEW ISSUE
В	03.12.22	MANUFACTURED BY DART
С	05.09.29	MS20426AD3-7 WAS MS20426AD3-5
***************************************		17.18

UNCONTROLLED COPY

SUBJECT TO AMENDMENT

WITHOUT NOTICE

WORK ORDER



D3193-041 SUPPORT BRACKET ASSEMBLY (D3193-1 SUPPORT BRACKET)

__ 1) MATERIAL: 6061-T6 ALUMINUM (QQ-A-225/8 OR QQ-A-200/8) (REF DART SPEC. M6061T6B)

2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1 POWDER COAT WHITE (4.3.5.1) PER DART QSI 005 4.3

3) BREAK ALL SHARP EDGES 0.005 TO 0.010

TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

Copyright © 2003 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

DART AEROSPACE LTD	Work Order:	35365A
Description: SUPPORT BRACKET	Part Number:	03193-1
Inspection Dwg: 03/93 Rev: C		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

	X	First Artic	le _	Prote	Prototype		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments	
3. 435	±010	3.436					
2.012	±.010	2.013		ļ			
1.200	±.016	1.200					
2.006	±. 016	2.003					
R 0.125	±.010	R.125					
2.435	±.00 5	2.433			-		
0.281	+.005	6.283		ļ			
0,264	±.010	0.260		ļ			
5.878	±.016	5.880		ļ			
4.878	±.005	4.877					
				ļ			
2.550	010	2.549		<u> </u>			
150	± 1/2°	150		<u> </u>			
0.260	±.010	,263			<u> </u>		
R 0.50	4.030	R.500			<u> </u>	· · · · · · · · · · · · · · · · · · ·	
80.266	±:00 6	80.272					
\$0.098	+.004	50.102		· .			
6.180 x 100°	+ .005	Ø.182×100					
0,850	±.010	0.857					
R0.125	+.010	R.125					
0.255	= 016	0.254		1			
2.812	1.016	2,812		·			
0.0.0				1		<u> </u>	
			111	/	Prototype Appro	val:	
Measured by: 4		Audited by:	1.11		JOIOTAPE White	TWIF .	

	Date:	08/02/12	Date: 08 02.12 Date:	
			Revised I	y Approved
Rev	Date	Change	1/2 D 3193-041 KJ/RF	
A		New Issue	1/0 9 7 (1) = 041	

